



Replace damaged chimney from throat up per Case 2 of CA standard plan SP-2 to match existing size, height + exterior painted brick appearance (cut existing brick into ~~3/4"~~ 1" veneer + re-install)

